

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



25/05 2004 16:36 FAX 95557762

433 FAX

004

Appln No. 10/727,157  
Amdt. Dated May 19, 2004  
Preliminary Amendment

2

**Amendments to the Specification:**

**The paragraph beginning at Page 10, please insert new line 30 as follows:**

**Figure 63A Timers sub-block partition diagram**

**The paragraph beginning at Page 10, please insert new line 32 as follows:**

**Figure 66 is a schematic of a timing pulse generator**

**The paragraph beginning at Page 16, line 5, to be amended as follows:**

**Figure 278 is intentionally omitted shows power on reset**

**The paragraph beginning at Page 18, line 39 to be amended as follows:**

**Figure 388A shows setup for multiple preauth fields**

Appln No. 10/727,157  
Amdt. Dated May 19, 2004  
Preliminary Amendment

3

**Amendments to the Drawings:**

Please delete Figure 413 on page 331 of the drawings and insert Figure 278 on page 237 of the drawings.